## Oil Field Environmental Incident Summary

**Date/Time of Notice:** 04/21/2015 08:33 Incident: 20150421083341 Responsible Party: XTO ENERGY INC. Well Operator: XTO ENERGY INC. Well Name: BIG GULCH FEDERAL 41X-16 Field Name: HAYSTACK BUTTE Well File #: 19072 Facility ID Number: DUNN **Rna**: 97 **Sec:** 16 **Qtr:** County: **Twp:** 148 Location Description: Submitted By: Shawn Dahl Received By: Contact Person: Shawn Dahl 2732 Hwy 85 N Alexander, ND 58831 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Other Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** 2 2 Oil Barrels Barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: none Areal Extent: none

## Potential Environmental Impacts:

none

## Action Taken or Planned:

The murphy gauge was replaced. Impacted material will be removed and taken to an approved disposal facility.

Wastes Disposal Location: The impacted material will be taken to an approved disposal facility.

Agencies Involved:

## **Updates**

Date: 4/21/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.